

**Flood Control Project Maintenance
Levee Inspections**

Fall 2011 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

RD2103	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2103 Wheatland Vicinity	A	9.77				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.17	
Animal Control	0.01		0.01	0.10%		
<i>LMA Totals:</i>	0.01	0.00	0.01	0.10%	0.17	0.00
Unit No. 01 South Dry Creek LB	Overall Unit Rating	Total Unit Miles				
RD2103	A	4.77				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
No Items						
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.00	0.00
Unit No. 02 Bear River RB	Overall Unit Rating	Total Unit Miles				
RD2103	A	5.00				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Encroachments					0.17	
Animal Control	0.01		0.01	0.20%		
<i>Unit Totals:</i>	0.01	0.00	0.01	0.20%	0.17	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2011 Levee Inspection Results

Reclamation District No. 2103 Wheatland Vicinity

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 2103 Wheatland Vicinity

Waterway			Bank	Unit Miles
Unit No. 01 South Dry Creek			Left	4.77
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	5/19/2011 - 5/19/2011		11/28/2011 - 11/28/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By	Tom Engler		Tom Engler	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 2103 Wheatland Vicinity

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	4.77	11/28/2011 11/28/2011	Clay Thomas

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.04	4.57	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	39.020042 ° -121.453334 °	39.041585 ° -121.394216 °	2 Y
2	0.04	4.57	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	39.020042 ° -121.453334 °	39.041585 ° -121.394215 °	1 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 2103 Wheatland Vicinity

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	4.77	11/28/2011 11/28/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.04
End Levee Mile	4.57
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This photo shows the waterside vegetation at levee mile 2.60.

cathom_f_20111201_030.jpg



Levee Mile Report Line	2
Start Levee Mile	0.04
End Levee Mile	4.57
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shows the landside vegetation at levee mile 2.60.

cathom_f_20111201_029.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 2103 Wheatland Vicinity

Waterway			Bank	Unit Miles
Unit No. 02 Bear River			Right	5.00
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	5/19/2011 - 5/19/2011		11/28/2011 - 11/28/2011	
DWR Inspector	Clay Thomas		Clay Thomas	
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 2103 Wheatland Vicinity

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 Bear River						Right	5.00	11/28/2011 11/28/2011	Clay Thomas	
LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.02	4.15	Earthen Levee	Vegetation	LS	A	Remove the wild growth other than native grasses from the levee slopes.	38.993527 ° -121.436953 °	39.023687 ° -121.377860 °	2 Y
2	0.02	4.15	Earthen Levee	Vegetation	WS	A	Remove the wild growth other than native grasses from the levee slopes.	38.993527 ° -121.436952 °	39.023687 ° -121.377860 °	3 Y
3	0.30	0.30	Earthen Levee	Rip Rap Revetments	WS	W	Inspector Comments: The District has a concern dead trees placed in the rip rap may not stay in place during a high water event.	38.994660 ° -121.432170 °	38.994660 ° -121.432170 °	4 Y
4	0.33	0.50	Earthen Levee	Encroachments	WS	PO	Landscaping	38.994787 ° -121.431728 °	38.995502 ° -121.428730 °	1 Y
5	0.68	0.68	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.996177 ° -121.425669 °	38.996177 ° -121.425669 °	6

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 2103 Wheatland Vicinity

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	5.00	11/28/2011 11/28/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.02
End Levee Mile	4.15
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shows the landside vegetation at levee mile 0.00.

cathom_f_20111201_027.jpg



Levee Mile Report Line	2
Start Levee Mile	0.02
End Levee Mile	4.15
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This photo shows the waterside vegetation at levee mile 0.00.

cathom_f_20111201_028.jpg



Levee Mile Report Line	3
Start Levee Mile	0.30
End Levee Mile	0.30
Location	Water Side
Category	Earthen Levee
Item	Rip Rap Revetments

Trees at waters edge in the rip rap levee mile 0.30.

cathom_f_20110929_656.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 2103 Wheatland Vicinity

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	5.00	11/28/2011 11/28/2011	Clay Thomas

Levee Mile Report Line	4
Start Levee Mile	0.33
End Levee Mile	0.50
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Levee mile 0.33, this photo is looking at the landscaping, vegetation on the waterside slope	
cathom_f_20110929_655.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing W : Watch/Monitor	N : Not Inspected, see Inspector Comment C : Corrected
--	--	--	---